

RANCHO LAS JUNTAS
SURVEYS OF CONTRA COSTA GOLF CLUB

- 1- 86PM32 6/6/80
- 2- POR 89PM6 9/5/80
- 3- 146PM21 5/7/90

95 LSM 27
04 LSM 15

89 LSM 22

VR 1045-01
VR 1078-99

128 LSM 31



VR 1015-12

114 LSM 32

88 LSM 28

MOVED FM. BK. 154,
PG. 15.

NOTE: THIS MAP WAS PREPARED FOR ASSESSMENT PURPOSES ONLY. NO LIABILITY IS ASSUMED FOR THE ACCURACY OF THE INFORMATION DELINEATED HEREON. ASSESSOR'S PARCELS MAY NOT COMPLY WITH LOCAL LOT SPLIT OR BUILDING SITE ORDINANCES.



190 48,49
10/13/22