CORNER RECORD City of ORINDA Brief Legal Description MONUMENT LOCATED WITHIN REFERENCE APN: 262-033-019 CORNER TYPE Government Corner Control Meander Property	9 (31 PM 11)	mber
Meander Property Other Date of Survey 03/30/2022		Units Metric U.S. Survey Pool Horizontal Datum Zone Epoch Date Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902
PLS Act Ref.: 8765 (d) X 8771 Corner/ X Left as found Established Monument: Found and tagged Reestablished	Rebuilt Referenced	Other: Pre-Construction Post-Construction
Narrative of corner identified and monument as found, set, reset, re See sheet #2 for description (s): FOUND 2" IRON PIPE. REFERENCED CENTER OF IMONUMENT BURIED 0.9' BELOW GRADE. EXCAVA FOUND AND SET POINTS AS SHOWN ON PAGE 2. THIS POINT WAS REFERENCED PRIOR TO A CONSTRUCTION PRIOR TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN HERE 21051-Camino Sobrante-CR-23 SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in confidence of the Professional Land Surveyors' Act on APRIL 06 Signed P.L.S. or R.C.E. No. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	PIPE. TED PRIOR TO ROJECT IN THE VIC TUATING FOUND M EON TO TRUE BOU	REFERENCING. CINITY. IONUMENTATION. NO CLAIM IS MADE AS
and examined and filed October 10 20	2022 022 No. 7438	SULAND SURVE OF A TREZIST OF A

County Surveyor's Comment