	RNER R	ECORD	Agency Index Document No County of	umber $\frac{1}{1}$	338 1184 tra costa		
Brief Legal De	escription MONU	MENT WELL LOCATED	WITHIN RHEEL	M BLVD	ANDO (05	14.00)	
	REFER	RENCE APN: 270-131-0 CORNER TYPE		EEM HIGHL	ORDINATES	(Optional)
	1	CORNER TITE	•				
	Governm	ent Corner X Contro	ŀ	Elevation		·	
	Meander	Proper	ty	Units	Metric	U.s	S. Survey Foot
	Rancho	Other		Horizontal Dat	um		
	_			Zone	Epoch D	ate	
	Date of S	Survey <u>03/31/2022</u>			1 %		
					with Public Reso with Public Reso		
PLS Act Ref.:	8765 (d)	X 8771	8773		Oth	er:	
Corner/	X Left as found	Established	Rebuilt		X Pre-	Construction	า
Monument:	Found and tagged	Reestablished	X Referenced		Pos	t-Constructio	on
See sheet #2 for description (s): FOUND 1.5" BRASS DISK WITH PUNCH IN MONUMENT WELL. STAMPED "CCCO RH 29". MONUMENT BURIED: LID 0.5' BELOW GRADE, DISK 1.15' BELOW LID. EXCAVATED PRIOR TO REFERENCING. FOUND AND SET POINTS AS SHOWN ON PAGE 2. THIS POINT WAS REFERENCED PRIOR TO A CONSTRUCTION PROJECT IN THE VICINITY. THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTATION. NO CLAIM IS MADE AS TO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN HEREON TO TRUE BOUNDARY LOCATION. 21051-Rheem Blvd-CR-22 SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with							
	Land Surveyors' Act on	2022	61 1 1 11				
(He Professional	14/1///	a terrolidad state of	8525		// //		/ - //
Signed	SCOTT V. CUNHA	P.L.S. or R.G.E. I			STA	E OF CALIF	(dept.)
	COUNTY SU	IRVEYOR'S STATEMENT	-	(
	cord was received and filed 10-10-2022 a.M. Jurgino rim County Su	4.13.2022, P.L.S. or R.C.E			*	SED LAND SANA M. T.	WELLISE *
County Surv	eyor's Comment	(45)			1/2	E 05 743	FORM