

CORNER RECORD


Agency Index 238 CR 37
Document Number CR 11200
County of CONTRA COSTA, California

City of ORINDA

Brief Legal Description MONUMENT LOCATED WITHIN LOMAS CANTADAS
REF APN: 265-100-006 150 LSM 21

CORNER TYPE

COORDINATES (Optional)



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

N. _____ E. _____
Elevation _____
Units Metric U.S. Survey Foot
Horizontal Datum _____
Zone _____ Epoch Date _____
Vertical Datum _____
 Complies with Public Resources Code §§8801-8819
 Complies with Public Resources Code §§8890-8902

Date of Survey 03/18/2022

PLS Act Ref.: 8765 (d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):
FOUND NAIL AND TAG LS 7136

FOUND AND SET POINTS AS SHOWN ON PAGE 2.
THIS POINT WAS REFERENCED PRIOR TO A CONSTRUCTION PROJECT IN THE VICINITY.
THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTATION. NO CLAIM IS MADE AS TO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN HEREON TO TRUE BOUNDARY LOCATION.
21051-Lomas Cantadas-CR-07

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on MARCH 25, 2022.
Signed *Scott V. Cunha* P.L.S. or R.C.E. No. 8525
SCOTT V. CUNHA



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 4.13.2022,
and examined and filed October 10, 2022.
Signed *Dana M. Trezise* P.L.S. or R.C.E. No. 7438
Title *Interim County Surveyor*
County Surveyor's Comment _____



LEGEND

- FOUND NAIL AND TAG LS 7136
- ✕ SET CUT CROSS IN VALLEY GUTTER
- ⊗ SET MAG NAIL AND TAG "CUNHA RP"
- SET REBAR & CAP "RP LS 8525"
- 5289 REFERENCE STREET ADDRESS

SCALE: 1"=30'



SCALE: 1" = 30'

ALL MEASUREMENTS IN U.S. SURVEY FEET AND DECIMAL THEREOF

