


CORNER RECORD

Agency Index 238 CR 39
Document Number CR 11202
County of CONTRA COSTA, California

City of ORINDA

Brief Legal Description MONUMENT LOCATED WITHIN LOMAS CANTADAS

REF APN: 265-100-006 150 LSM 21



- CORNER TYPE
- Government Corner
 - Meander
 - Rancho
 - Control
 - Property
 - Other

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

Date of Survey 04/01/2022

- PLS Act Ref.: 8765 (d) 8771 8773 Other:
- Corner/Monument: Left as found Established Rebuilt Pre-Construction
- Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):

FOUND NAIL AND TAG LS 7136.

FOUND AND SET POINTS AS SHOWN ON PAGE 2.

THIS POINT WAS REFERENCED PRIOR TO A CONSTRUCTION PROJECT IN THE VICINITY.

THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTATION. NO CLAIM IS MADE AS TO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN HEREON TO TRUE BOUNDARY LOCATION.

21051-Lomas Cantadas-CR-05

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on APRIL 6, 2022.

Signed *Scott V. Cunha* P.L.S. or R.C.E. No. 8525

SCOTT V. CUNHA



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4.13.2022 and examined and filed October 10, 2022.

Signed *Dana M. Trejise* P.L.S. or R.C.E. No. 7438

Title *Interim County Surveyor*


County Surveyor's Comment _____



LEGEND

- FOUND NAIL AND TAG LS 7136
- ⊗ SET CUT CROSS IN DRIVEWAY
- ✕ SET CUT CROSS IN CONCRETE
- SET REBAR & CAP "RP LS 8525"
- 5289 REFERENCE STREET ADDRESS

SCALE: 1"=30'



SCALE: 1" = 30'

ALL MEASUREMENTS IN U.S. SURVEY FEET AND DECIMAL THEREOF

