


CORNER RECORD

Agency Index 238 CR 43
Document Number CR 11206
County of CONTRA COSTA, California

City of ORINDA

Brief Legal Description MONUMENT LOCATED WITHIN LOMAS CANTADAS
REF APN: 265-100-004 137 LSM 12



- CORNER TYPE
- Government Corner
 - Meander
 - Rancho
 - Control
 - Property
 - Other

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

Date of Survey 03/18/2022

- PLS Act Ref.: 8765 (d) 8771 8773 Other: _____
- Corner/Monument: Left as found Established Rebuilt Pre-Construction
- Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):

FOUND RAILROAD SPIKE WITH PUNCH

FOUND AND SET POINTS AS SHOWN ON PAGE 2.

THIS POINT WAS REFERENCED PRIOR TO A CONSTRUCTION PROJECT IN THE VICINITY.

THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING FOUND MONUMENTATION. NO CLAIM IS MADE AS TO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN HEREON TO TRUE BOUNDARY LOCATION.

21051-Lomas Cantadas-CR-01

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on MARCH 25, 2022.

Signed *Scott V. Cunha* P.L.S. or R.C.E. No. 8525

SCOTT V. CUNHA



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 13, 2022

and examined and filed October 10, 2022.

Signed *Dana M. Trezise* P.L.S. or R.C.E. No. 7438

Title Interim County Surveyor


County Surveyor's Comment _____





LEGEND

- FOUND RAILROAD SPIKE WITH PUNCH
- SET REBAR & CAP "RP LS 8525"
- ⑤289 REFERENCE STREET ADDRESS



SCALE: 1" = 30'

ALL MEASUREMENTS IN U.S. SURVEY FEET AND DECIMAL THEREOF

